

Check MOT history (<https://www.gov.uk/check-mot-history>)


WG06GXZ

VOLKSWAGEN LT

| | | |
|--------------|---------------|---------------------|
| Colour | Fuel type | Date registered |
| White | Diesel | 14 July 2006 |

MOT valid until
10 August 2019

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate 

| | | |
|----------------------|----------------------|-----------------------|
| Date tested | Mileage | MOT test number |
| 9 August 2018 | 305,564 miles | 5046 2797 2460 |
| PASS | Test location | Expiry date |
| | | 10 August 2019 |

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Body has slight corrosion**
- **Nearside Seat belt slightly damaged (7.1.2 (b) (i))**

| | | |
|---------------------|----------------------|-----------------------|
| Date tested | Mileage | MOT test number |
| 30 July 2018 | 304,623 miles | 6715 5633 6806 |
| FAIL | Test location | |

Do not drive until repaired (dangerous defects):

- **Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**

Repair immediately (major defects):

- Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Horn not working (7.7 (a) (ii))
- Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Rear fog lamp not working (4.5.1 (a) (ii))
- Offside Front Position lamp not working (4.2.1 (a))
- Nearside Front Seat belt retracting mechanism defective (7.1.2 (e))
- Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Repair as soon as possible (minor defects):

- Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Monitor and repair if necessary (advisories):

- Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Body has slight corrosion

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
4 August 2017

PASS

Mileage
291,499 miles

Test location

MOT test number
8840 3482 6928

Expiry date
10 August 2018

Advisory notice item(s)

- Body has slight corrosion (6.1.B.2)
- Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Crack on windscreen but not seriously effecting drivers view of the road
- Offside Steering rack gaiter deteriorated (2.2.D.2d)

Date tested
26 July 2017

FAIL

Mileage
291,499 miles

Test location

MOT test number
2914 0700 8229

Reason(s) for failure

- **Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**
- **Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**
- **Registration plate lamp not working both (1.1.C.1d)**
- **Nearside Side repeater not working (1.4.A.2c)**
- **Nearside Front Tyre has ply or cords exposed on the inner (4.1.D.1b)**
- **Horn not working (1.6.2a)**
- **Rear Exhaust has a major leak of exhaust gases (7.1.2)**
- **Parking brake: efficiency below requirements (3.7.B.7)**

Advisory notice item(s)

- **Body has slight corrosion (6.1.B.2)**
- **Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**
- **Crack on windscreen but not seriously effecting drivers view of the road**
- **Offside Steering rack gaiter deteriorated (2.2.D.2d)**

Date tested

10 August 2016

PASS

Mileage

291,499 miles

Test location

MOT test number

2612 2880 9819

Expiry date

10 August 2017

Advisory notice item(s)

- **Offside Steering rack gaiter deteriorated (2.2.D.2d)**
- **Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**
- **Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**

Date tested

2 August 2016

FAIL

Mileage

291,499 miles

Test location

MOT test number

2685 9700 0294

Reason(s) for failure

- **Horn not working (1.6.2a)**
- **Windscreen washer provides insufficient washer liquid (8.2.3)**
- **Nearside Front position lamp(s) not working (1.1.A.3b)**
- **Offside Front position lamp(s) not working (1.1.A.3b)**
- **Registration plate lamp not working Both (1.1.C.1d)**

- Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Brake load sensing valve seized (3.6.E.3)
- Brake load sensing valve linkage defective and function impaired (3.6.E.3)
- Nearside Steering rack gaiter split (2.2.D.2d)

Advisory notice item(s)

- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Offside Steering rack gaiter deteriorated (2.2.D.2d)
- Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Date tested
11 August 2015

Mileage
255,501 miles

MOT test number
2339 4890 0213

PASS

Test location

Expiry date
10 August 2016

Date tested
4 August 2015

Mileage
254,697 miles

MOT test number
6671 2601 5208

FAIL

Test location

Reason(s) for failure

- Registration plate lamp not working (1.1.C.1d)
- Nearside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Offside rear parking brake recording little or no effort (3.7.B.6a)
- Parking brake: efficiency below requirements (3.7.B.7)

Date tested
6 August 2014

Mileage
215,679 miles

MOT test number
7899 3861 4205

PASS

Test location

Expiry date
5 August 2015

Advisory notice item(s)

- Offside Front Shock absorber has a light misting of oil (2.7.3)

Date tested
1 August 2014

FAIL

Mileage
215,033 miles

MOT test number
2098 3321 4293

Test location

Reason(s) for failure

- **Nearside Front Headlamp not working on main beam (1.7.5a)**
- **Offside Front Headlamp not working on main beam (1.7.5a)**
- **Nearside Registration plate lamp not working (1.1.C.1d)**
- **Offside Registration plate lamp not working (1.1.C.1d)**
- **Offside Front position lamp(s) not working (1.1.A.3b)**
- **Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**
- **Brake load sensing valve linkage defective and function impaired (3.6.E.3)**
- **Parking brake: efficiency below requirements (3.7.B.7)**

Advisory notice item(s)

- **Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**
- **Offside Front Shock absorber has a light misting of oil (2.7.3)**

Date tested
23 July 2013

PASS

Mileage
175,013 miles

MOT test number
2071 8430 3246

Test location

Expiry date
5 August 2014

Date tested
18 July 2013

FAIL

Mileage
174,395 miles

MOT test number
2394 0919 3404

Test location

Reason(s) for failure

- **Registration plate lamp not working (1.1.C.1d)**
- **Nearside Front position lamp(s) not working (1.1.A.3b)**
- **Nearside Front Lower Ball joint has excessive play (2.2.B.1f)**
- **Brake load sensing valve linkage obviously incorrectly adjusted (3.6.E.3)**
- **Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**

Advisory notice item(s)

- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**
- **Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**

Date tested
6 August 2012

PASS

Mileage
139,948 miles

Test location

MOT test number
4894 9911 2298

Expiry date
5 August 2013

Advisory notice item(s)

- **Brake valve corroded but not excessively weakened (3.6.A.2b)**
- **Offside Front Steering rack gaiter deteriorated (2.2.D.2d)**
- **Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**
- **Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**
- **Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**
- **Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**

Date tested
11 July 2011

PASS

Mileage
114,491 miles

Test location

MOT test number
2379 0239 1402

Expiry date
14 July 2012

Advisory notice item(s)

- **Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**
- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**

Date tested
6 July 2011

FAIL

Mileage
114,483 miles

Test location

MOT test number
1160 2708 1130

Reason(s) for failure

- **Nearside Steering rack gaiter split (2.2.D.2d)**

- **Offside Front All position lamps not working (1.1.A.3b)**
- **Nearside Rear position lamp(s) insecure (1.1.A.3a)**
- **Front Windscreen washer provides insufficient washer liquid (8.2.3)**

Advisory notice item(s)

- **Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**
- **Nearside Front Tyre worn close to the legal limit (4.1.E.1)**

Date tested
15 July 2010

Mileage
98,311 miles

MOT test number
1428 7619 0150

PASS

Test location

Expiry date
14 July 2011

Advisory notice item(s)

- **Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**
- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Front Front wheel bearing has slight play (2.5.A.3c)**
- **Offside Front Front wheel bearing has slight play (2.5.A.3c)**
- **Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**

Date tested
15 July 2010

Mileage
98,311 miles

MOT test number
2240 6649 0469

FAIL

Test location

Reason(s) for failure

- **Windscreen washer provides insufficient washer liquid (8.2.3)**
- **Driver's seat insecure (6.2.A.1)**

Advisory notice item(s)

- **Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**
- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Nearside Front Front wheel bearing has slight play (2.5.A.3c)**
- **Offside Front Front wheel bearing has slight play (2.5.A.3c)**

- **Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**
-

Date tested
13 July 2009
PASS

Mileage
75,864 miles

MOT test number
1703 8459 9147

Test location

Expiry date
14 July 2010

Advisory notice item(s)

- **Adjustable towbar locating pin slightly worn (6.6.5b)**
 - **Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**
 - **Hand brake has long travel**
-

Outstanding vehicle recalls

Check if VOLKSWAGEN LT WG06GXZ has outstanding recalls



No outstanding safety recalls found

There are no outstanding manufacturer's safety recalls for **VOLKSWAGEN LT WG06GXZ**.

There can be a delay before we receive information about safety recalls. If you are concerned, contact your vehicle manufacturer's dealership.

Was this vehicle recall information useful to you? so we can improve the service.

Using Vehicle Recall Information

DVSA and its suppliers try to ensure that the information published on this website is accurate. However, as the information is aggregated from various sources, we can't accept any liability for the accuracy of content. This service provides an indicative check for outstanding safety recalls as at the date specified. Visitors and customers who rely on this information do so at their own risk. Visitors and customers are strongly encouraged to independently verify the information before acting or deciding not to act on that information.

The recalls data is obtained through a third party. The terms and conditions for the data can be found on by selecting the 'terms and conditions' link.
