



Address:
Postal address:
Phone:
Fax:
E-mail:
Homepage:

Mechanic:
Date: 02/08/2022
Car licence no:
VIN:
Mileage:
Vehicle: Ford - Fiesta [13-] - 2014

Fault codes

Instrument (Instrument - IPC (Instrument panel control module))

DTC	Description
P1607	- MIL Output Circuit - No message - Current
B10D7	- Key PATS (Passive anti theft system) - Activation fault - Current
U0100	- Lost communication with ECM/PCM "A" - No message - Current
U0121	- Lost Communication With Anti-Lock Brake System (ABS) Control Module - No message - Current

Restraints (Airbag - RCM (Restraint control module))

DTC	Description
B00D5	- Restraint System Passenger Disable Indicator - Short circuit to ground - Current
B1202	- Restraint System Passenger Enable Indicator - Short circuit to ground - Current
B0001	- Airbag, driver, stage 1 - Open circuit - Current
B0010	- Airbag, passenger, stage 1 - Open circuit - Current
B0004	- Driver's knee bolster deployment control - Open circuit - Current
U0100	- Lost communication with ECM/PCM "A" - No symptom - Current
80DF	- Unknown fault code
B11D8	- Airbag impact data - Short circuit to ground or open circuit - Current
U0423	- Invalid data received from instrument panel control module - No symptom - Current
U2300	- Central Configuration - Faulty signal - Current

Multifunction (ACM (Audio control module) - Diagnose)

DTC	Description
	No fault codes

Multifunction (APIM (Accessory protocol interface module) - Diagnose)

DTC	Description
	No fault codes

Multifunction (BCMii (Body control module) - Diagnose)

DTC	Description
B1097	- Heated windshield relay - Short circuit to ground or open circuit - Current
9A78	- Unknown fault code
U0121	- Lost Communication With Anti-Lock Brake System (ABS) Control Module - No symptom - Current
U0199	- Lost Communication With Door Control Module A - No symptom - Current
U0200	- Lost Communication With Door Control Module B - No symptom - Current
U0415	- Invalid data received from ABS control module - Event information - Current
U2005	- Vehicle speed - Message error - Current

Multifunction (FCDIM (Front Control/Display Interface Module) - Diagnose)

DTC	Description
	No fault codes

Multifunction (PSCM (Power steering Control Module) - Diagnose)

DTC	Description
U0100	- Lost communication with ECM/PCM "A" - No symptom - Current
U3002	- Vehicle identification VIN - Comparison error - Current
U0121	- Lost Communication With Anti-Lock Brake System (ABS) Control Module - No symptom - Current

